Haley & Aldrich, Inc. 8899 Gander Creek Drive Miamisburg, OH 45342-5432

Tel: 937.384.9940 Fax: 937.384.9946 HaleyAldrich.com



Letter of Transmittal

Date	17 January 2008
File Number	26708
From	Susan Hoertt, R.S., CPEA
То	U.S. EPA Region V Emergency Response Branch Command Post 919 Keowee Street Dayton, OH 45404
Attention	Steve Renninger, On-Scene Coordinator
Copy to	Randy Kirkland, Weston Solutions
Subject	Delphi Home Avenue Phase I SSD System Photos
Copies	Date Description
1	17 January CD 2008
Transmitted via	☐ First class mail ☐ Overnight express ☒ Hand delivery ☐ Other

Remarks

Per your request, Haley & Aldrich, on behalf of Delphi Corporation, is providing you one CD copy of photographs of the exterior components of the Delphi Home Avenue Phase I SSD system installation.

Please contact Susan Hoertt at 937.530.1408 if you have any questions concerning this matter.



Photo 1 Ex. 6 P... Names, Address... — front (west side) of property.



Photo 2: Ex. 6 P... Names, Address... – rear (east side) of property. Note unsecured property with broken windows and doors ajar.



Photo 3: Ex. 6 P... Names, Addresses... rear (east side) of property. Note unsecured property with windows broken and door ajar.




Photo 4: Ex. 6 P... Names, Addr... – north side of property. Note unsecured property with door ajar.




Photo 5: Ex. 6 P... Names, Addre... – rear (east side) of property. Note unsecured property with door ajar.



Photo 6: Ex. 6 P... Names, Addr... – front (west side) of property.



Ex. 6 P... Na...

Photo 7: Ex. 6 P... Names, Addr... – back (east side) of property. Note broken window, evidence of possible fire damage, and City of Dayton Department of Building Services boarding and notice, "Presence on these Premises Prohibited."

Attachment 4 Delphi VOC Plume Site - Uninhabitable Structures




Photo 8: Ex. 6 P... Names, Addresses... north side of property. Note unsecured property with door ajar.




Photo 9: Ex. 6 P... Names, Addre... — north side of property. Note unsecured property with door ajar.



Photo 10 Ex. 6 P... Names, Addre... – front (west side) of property. Note broken windows and City of Dayton Department of Building Services boarding and notice, "Presence on these Premises Prohibited."



Photo 11: Ex. 6 P... Names, Ad... – front (east side) of property. Note City of Dayton Department of Building Services boarding.



Photo 12 Ex. 6 P... Names, Addr... – front (west side) of property. Note broken windows, apparent structural damage, City of Dayton Department of Building Services boarding and notice, "Public Nuisance, No Occupancy, No Trespassing."



Photo 13 Ex. 6 P... Names, Addresses a... – front (west side) of property. Note unsecured property with broken windows, missing door, apparent structural damage, and City of Dayton Department of Building Services boarding and notice, "Presence on these Premises Prohibited."



Photo 14: Ex. 6 P... Names, Addresses and phon... – front (west side) of property. Note unsecured property with broken windows, missing door and accumulation of material blocking entrance.



Photo 15: Ex. 6 P... Names, Addresses and ph...

- front (southwest side) of property,
Note missing door, window ajar,
apparent structural damage, and
City of Dayton Department of
Building Services boarding and
notice.



Photo 16: Ex. 6 P... Names, Addresses and phone... – front (west side) of property. Note unsecured property.



Photo 17: Ex. 6 P... Names, Addresses and pho... – front (southwest side) of property. Note unsecured property and possible structural damage.